



10/30/2024

In 2021, the US Environmental Protection Agency issued Lead and Copper Rule Revisions (LCRR). One key element of this action was requiring all water systems across the country to inventory service lines connected to their systems to determine if lead pipes are present before October 2024. Over the last two years, Avion has completed an inventory of all our water systems (named below), and we are pleased to report that No Lead Service Lines were found.

Name of Avion Water System	
Brasada Ranch	Red Cloud
Chaparral	South Redmond Heights
Cinder Butte Estates	Sun Country Water (Saddleback)
Desert Springs	Tetherow Crossing
DRID (Deschutes River Improvement District)	Tumalo Rim
Greater Avion	Tumalo West
Happy Acres	Turner
Highland Estates	Tuscarora
Long Butte	Whychus Creek (Squaw Creek Canyon Estates)
Odin Falls	Wild River

We determined this through a combination of approved methods including the date of subdivision plat, date structure was built or service installed, manual or visible inspection or excavation at the meter pit, and statistical/predictive analysis. Inspections will be ongoing for service lines that we used the statistical/predictive methodology on.

This project requires water systems to make information collected publicly available. Individual system inventory lists are extensive and viewable upon request in our office. Please reach out to us at avion@avionwater.com or 541-382-5342 if you have any questions.