

## King David Ave Affected Area

02-02-26

Due to an emergency system repair in the King David Ave area, a precautionary boil water notice has been issued. If you are receiving this message the advisory is applicable to you. You will be contacted again when this advisory is lifted. If you have further questions, please call our office at 541-382-5342 or visit our website at [avionwater.com](http://avionwater.com).

### ADDRESS

20848 KING DAVID AVE  
20856 KING DAVID AVE  
20857 KING DAVID AVE  
20864 KING DAVID AVE  
20865 KING DAVID AVE  
20870 KING DAVID AVE  
20873 KING DAVID AVE  
20876 KING DAVID AVE  
20882 KING DAVID AVE  
61303 KING JOSIAH PL  
61304 KING JOSIAH PL  
61315 KING JOSIAH PL  
61316 KING JOSIAH PL  
61320 KING JOSIAH PL  
61325 KING JOSIAH PL  
61330 KING JOSIAH PL  
61331 KING JOSIAH PL  
61339 KING JOSIAH PL  
61340 KING JOSIAH PL  
61345 KING JOSIAH PL  
61349 KING JOSIAH PL

## Precautionary Boil Water Area

