

Sunset West/Hwy 20 Area Boil Notice

Effective 11/30/2022 - TBD

Your area near Sunset West/Highway 20 is under a boil water notice due a planned system upgrade and loss of line pressure. If you received this message the advisory is applicable to you. You will be contacted again when this advisory is lifted, If you have further questions, please call our office at 541-382-5342

SERVICE LOCATIONS:


19980 DESTINY CT
19990 DESTINY CT
19995 DESTINY CT
20025 DESTINY CT
20058 SUNGLOW CT
20063 SUNGLOW CT
20063 SUNSET PL
20066 SUNGLOW CT
20066 SUNSET PL
20069 SUNSET PL
63750 OB RILEY RD
63775 OB RILEY RD
63795 OB RILEY RD
63810 OB RILEY RD
63811 OB RILEY RD
63812 OB RILEY RD
63823 OLD BEND REDMOND HWY
63833 OB RILEY RD
63848 MIDAY WAY
63849 MIDAY WAY
63850 OLD BEND REDMOND HWY
63853 MIDAY WAY, house
63853 MIDAY WAY, mobile
63855 SUNSET DR
63861 SUNSET DR
63866 SUNSET DR

63869 SUNSET DR
63876 SUNSET DR
63877 SUNRISE CIR
63880 SUNRISE CIR
63886 SUNRISE CIR
63887 SUNRISE CIR
63890 SUNSET DR
63893 SUNSET DR
63894 SUNRISE CIR
63899 SUNRISE CIR
63900 SUNRISE CIR
63900 SUNSET DR
63905 SUNRISE CIR
63905 SUNSET DR
63910 OLD BEND REDMOND HWY
63911 SUNRISE CIR
63911 SUNSET DR
63912 SUNSET DR
63914 SUNRISE CIR
63917 SUNSET DR
63919 SUNRISE CIR
63922 SUNSET DR
63924 SUNSET DR
63925 SUNSET DR
63926 SUNSET DR
63928 SUNSET DR
63929 SUNSET DR

63930 OLD BEND REDMOND HWY
63939 SUNSET DR
63944 SUNSET DR
63949 SUNSET DR
63959 SUNSET DR
63960 SUNSET DR
63970 SUNSET DR
63973 SUNSET DR
63980 SUNSET DR
63984 SUNSET DR
63987 SUNSET DR
63990 OB RILEY RD
64020 OB RILEY RD
64025 HWY 20
64030 OB RILEY RD
64040 OB RILEY RD
64056 OB RILEY RD
64141 HWY 20
64169 HWY 20

Precautionary Boil Water Area



 Affected Area
 Taxlot

Bureau of Land Management, State of Oregon, State of Oregon DOT, State of Oregon GEO, Esri, Canada, Esri, HERE, Garmin, GeoTechnologies, Inc., USGS, METI/NASA, EPA, USDA

